

June 2026

To Whom It May Concern:

Safety Data Sheets are required for materials that (a) meet the definition of hazardous and (b) are known to be present in the workplace in such a manner that employees may be exposed under normal conditions of use or a foreseeable emergency as defined under OSHA's Hazard Communication Standard (29 CFR 1910.1200).

X-ray tubes and flat panel detectors are "articles" under the OSHA's Hazard Communication Standard, which is aligned with the Globally Harmonized System of Classification and labelling of Chemicals (GHS). Articles are outside the scope of Hazard Communication and, therefore, do not require an SDS.

An article: "a manufactured item other than a fluid or particle: (i) which is formed to a specific shape or design during manufacture; (ii) which has end used function(s) dependent in whole or in part upon its shape or design during end use; and (iii) which under normal conditions of use does not release more than very small quantities, e.g., minute or trace amounts of a hazardous chemical...and does not pose a physical hazard of health risk to employees."

Under normal conditions of use and foreseeable emergencies, X-ray tubes and flat panel detectors do not result in employee exposure to hazardous chemicals.

For further information and clarification, please refer to OSHA's Hazard Communication Standard:

29 CFR [1910.1200 - Hazard Communication](https://www.osha-slc.gov/29CFR1910.1200-Hazard-Communication). | [Occupational Safety and Health Administration \(osha.gov\)](https://www.osha-slc.gov/)

Additionally, X-ray tubes and flat panel detectors are not classified as **dangerous goods** under **OMDG** or **IATA** regulations.

Sincerely,

A handwritten signature in cursive script that reads "Laurie Jensen".

Laurie Jensen
Regulatory Affairs Manager
Varex Imaging Corporation
1678 South Pioneer Road
Salt Lake City, UT 84104 USA