

Contract Number: 710383

**Certificate of Compliance: SGSNA/18/GER/00055**

Certificate Project Number: GER-CERT180900127

**Certified Product:**

**Collimator**

**Trademarks (if any):**

Claymount and/or Varex Imaging

**Model(s):**

Optica 10 series

**Technical Data:**

12 – 45 VDC, 24 VA and/or 24 VDC, 24 VA  
and/or 20 – 30 VAC, 35 VA; 50/60 Hz

**Name and Address of Certificate Holder:**

Varex Imaging Nederland B.V.  
Anholtseweg 44, 7091 HB, Dinxperlo, The Netherlands

**Name and Address of Manufacturer:**

Varex Imaging Nederland B.V.  
Anholtseweg 44, 7091 HB, Dinxperlo, The Netherlands



This certificate supercedes previous certificates issued with the same certificate number. Certification is valid when products are indicated on the SGS directory of certified products at [www.sgs.com](http://www.sgs.com). The product is certified according to ISO/IEC Guide 17067, *Conformity assessment - Fundamentals of product certification, System 3*, and in accordance with

**ANSI/AAMI ES60601-1:2005 +C1 (2009) +A1 (2012) +A2 (2010)**

**CAN/CSA C22.2 No. 60601-1:14**

**CAN/CSA C22.2 No. 60601-1-3-09 Rev., 11/01/2009**

**IEC 60601-1-3:2008 + A1:2013**

**IEC 60601-1-6:2010 + A1:2013**

**CAN/CSA C22.2 No. 60601-2-54: 2011 + A1:2017**

**IEC 60601-2-54:2009 + A1:2015**

Authorized by

Effective date: 09 July 2019

  
Paul Krauss  
Certifier

Consumer and Retail Services, a division of SGS North America Inc.

620 Old Peachtree Road, Ste. 100, Suwanee, GA 30024, USA

t +1 770 570 1800 f +1 770 277 1240 [www.sgs.com](http://www.sgs.com)

Page 1 of 2



This certificate is issued by the company under its General Conditions for Certification Services accessible at [www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitations of liability defined therein and in the Test Report here above mentioned which findings are reflected in this Certificate. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Contract Number: 710383

**Certificate of Compliance: SGSNA/18/GER/00055**

Certificate Project Number: GER-CERT180900127

**Certified Product:**

**Collimator**

**Trademarks (if any):**

**Claymount and/or Varex Imaging**

**Model(s):**

**Optica 10 series**

**Name of Certificate Holder:**

**Varex Imaging Nederland B.V.**

**Name and Address of Factory:**

**Varex Imaging Nederland B.V.  
Anholtseweg 44, 7091 HB, Dinxperlo, The Netherlands**

**Effective date: 09 July 2019**

Consumer and Retail Services, a division of SGS North America Inc.  
620 Old Peachtree Road, Ste. 100, Suwanee, GA 30024, USA  
t +1 770 570 1800 f +1 770 277 1240 www.sgs.com  
Page 2 of 2



This certificate is issued by the company under its General Conditions for Certification Services accessible at [www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitations of liability defined therein and in the Test Report here above mentioned which findings are reflected in this Certificate. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.